



A
 QTY 3
 MAWN 2832 ROTO
 SCALE: 1/2" = 1'-0"
 6-9/16" JAMBS




C
 QTY 3
 WUDH 2424
 SCALE: 1/2" = 1'-0"
 6-9/16" JAMBS
 TEMPERED




D
 WUDHTR 4012
 QTY 3 SCALE: 1/2" = 1'-0"

6-9/16" JAMBS
 TEMPERED




E
 WAWN 4832 ROTO
 QTY 2 SCALE: 1/2" = 1'-0"


4-9/16" JAMBS




F1
 QTY 2
 WAWN 3640 ROTO
 SCALE: 1/2" = 1'-0"
 4-9/16" JAMBS
 ELECTRIC OPERATOR




F2
 QTY 2
 WAWN 3640 STAT
 SCALE: 1/2" = 1'-0"
 4-9/16" JAMBS



H
 QTY 1
 WAWN 2832-2 ROTO
 SCALE: 1/2" = 1'-0"
 6-9/16" JAMBS



J
 QTY 1
 WUDH 2424-2W
 SCALE: 1/2" = 1'-0"
 6-9/16" JAMBS



L
 QTY 2
 WCM 3656 LH
 SCALE: 1/2" = 1'-0"
 6-9/16" JAMBS
 VERIFY HANDING